

Oil Field Environmental Incident Summary

Incident: 20151006145218 **Date/Time of Notice:** 10/06/2015 14:52

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: BRAYDEN ALEXANDER 20-17H

Field Name: WRITING ROCK

Well File #: 26426

Date Incident: 10/5/2015 **Time Incident:** 12:00

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 101

Sec: 20

Qtr: SW SE

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels	30	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Unit is shut down. Vacuum truck called for clean up, delayed by road restriction. Repairs to commence after cleanup.

Wastes Disposal Location: production tank

Agencies Involved:

Updates

Date: 10/7/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to pump leak, remained on location within the diking according to the report. NDIC retains oversight.